ชื่อเรื่องวิทยานิพนธ์

การเกาะติดของอื่นาเมลโดยพันธะเคมีระหว่างผิวแก้วกับโลหะ

ชื่อผู้เขียน

นางสาวปียนันท์ บุญอริยเทพ

วิทยาศาสตรมหาบัณฑิต

สาขาวิชาเคมี

คณะกรรมการสอบวิทยานิพนธ์ รองศาสตราจารย์ ดร.ประสักดิ์ ถาวรยุติการต์ ประธานกรรมการ รองศาสตราจารย์ ดร.กาญจนะ แก้วกำเนิด กรรมการ รองศาสตราจารย์ ชิติพันธุ์ ทองเต็ม กรรมการ

บทคัดย่อ

ได้ศึกษาการเกาะติดชั้นระหว่างผิวของแก้วตะกั่วอื่นาเมลและโลหะทองแดง ที่ได้เผาถึง อุณหภูมิไม่เกินกว่า 900 องศาเซลเซียส ในบรรยากาศออกซิเดชัน จากหลักฐานของเอกซเรย์ ดิฟแฟรกซันและเอกซเรย์ฟลูออเรสเซนส์ พบว่ามีการเชื่อมโยงทางเคมีระหว่างแก้วและทองแดง ซึ่งแสดงให้เห็นจากการมืองค์ประกอบของออกไซค์ทองแดง เช่น CuO และ Cu2O รวมกับสาร เชิงซ้อนที่อาจเรียกว่าโลหะผสม และอาจมืองค์ประกอบแบบเมทริกซ์ อันเป็นลักษณะเฉพาะ ของการเกิดเดนไดรท์และตกจมลงรวมกันของสารประกอบของตะกั่ว โบรมีน ทองแดง โคบอลท์ และ แมงกานีส ได้ทำการศึกษาการเกาะติดระหว่างชั้นผิว ซึ่งมีปัญหาการเกิดฟองอากาศ และ รอยแตกบนผิวผลิตภัณฑ์อื่นาเมล พบว่าอาจเกิดจากสาเหตุขององค์ประกอบเคลือบ การกระจาย ขนาดของอนุภาคเคลือบ รูปร่างที่มีผิวขรุขระของโลหะ และความหนาของโลหะทองแดง

Thesis Title

Adherence of Enamel by Chemical Bonding at Glass-Metal

Interface

Author

Piyanun Boonariyatep

M.S.

Chemistry

Examining Committee

Assoc. Prof. Dr. Prasak Thavornyutikarn

Chairman

Assoc. Prof. Dr. Kanchana Keowkamnerd

Member

Assoc. Prof. Titipun Thongtem

Member

ABSTRACT

The interface between lead-enamel glass and the copper metal which had been fired to a temperature not exceeding 900°C in an oxidation atmosphere was studied. From the X-ray diffraction and X-ray fluorescence, it showed the composition of copper oxide as CuO and Cu₂O with a copper complex which may be called metal alloy. These evidences indicated the chemical binding between glass and copper. A matrix of components which may be characterized by the formation of dendrite and the precipitation of the compounds of Pb, Br, Cu, Co and Mn was also possible. Adherence at the interface was studied to clarify the problems of air bubble formation and cracking on surface enamel products. It was found that these could be caused by the composition, particle size distribution of glazes, and roughed surface shape and thickness of the metal.