ชื่อเรื่องการค้นคว้าแบบอิสร**ะ**

แนวทางการป้องกันอุบัติภัยในการฝึกงานของนักศึกษา

โรงเรียนเชียงใหม่เทคโนโลยี

ชื่อผู้เขียน

นายมารุศ ภู่พานิชเจริญกูล

สึกษาศาสตรมหาบัณฑิต

สาขาวิชาอาชีวศึกษา

คณะกรรมการสอบการค้นคว้าแบบอิสระ

ผู้ช่วยศาสตราจารย์ ดร.กัญญา กำศิริพิมาน ประธานกรรมการ ผู้ช่วยศาสตราจารย์มนูญ สุตีคา กรรมการ

ผู้ช่วยศาสตราจารย์อภิชาติ เมฆบังวัน

กรรมการ

บทคัดย่อ

การศึกษาครั้งนี้มีวัตถุประสงค์ เพื่อศึกษาปัจจัยที่ก่อให้เกิดอุบัติภัยและศึกษาหาแนวทาง การป้องกันการเกิดอุบัติภัยในการฝึกงานของนักศึกษาโรงเรียนเชียงใหม่เทคโนโลยี ได้รวบรวม ข้อมูลโดยใช้แบบสอบถามครูผู้สอนประเภทวิชาช่างอุตสาหกรรม ทั้งหมด จำนวน 130 คน นักเรียน นักศึกษา ที่เคยได้รับอุบัติภัยระหว่างปีการศึกษา 2540-2541 จำนวน 28 คน เครื่องมือ ที่ใช้ในการศึกษาเป็นแบบสอบถามที่ผู้เขียนทำการสร้างขึ้นมาเอง การวิเคราะห์ข้อมูลใช้การแจก แจงความถี่ คำนวณค่าร้อยละ ค่าเฉลี่ย และส่วนเบี่ยงเบนมาตรฐาน

ผลการศึกษาพบว่า ความคิดเห็นเกี่ยวกับปัจจัยที่ก่อให้เกิดอุบัติภัยในการฝึกงานเกิดจาก การกระทำที่ไม่ปลอดภัย เช่นขาดกวามรู้ในเรื่องความปลอดภัย การไม่ปฏิบัติตามกฎ ระเบียบ ความปลอดภัยในการทำงาน และการทำงานโดยไม่ใช้อุปกรณ์ป้องกันอันตรายส่วนบุคคล และ สภาพการที่ไม่ปลอดภัย เช่นเครื่องจักรไม่มีเครื่องกำบังหรืออุปกรณ์ป้องกันอันตรายขาดการดูแล รักษาซ่อมแชมเครื่องจักรให้อยู่ในสภาพใช้งานได้อย่างมีประสิทธิภาพ

ความคิดเห็นแนวทางการป้องกันการเกิดอุบัติเหตุในการฝึกงาน การกำหนดนโซบาย ค้านความปลอดภัยควรมีทิสทางชัดเจน และการเสริมสร้างให้ครูมีจิตสำนึกเรื่องความปลอดภัยขึ้น การสอนให้คระหนักถึงอันตรายที่เกิดขณะฝึกปฏิบัติ และปฏิบัติตามกฎ ระเบียบอย่างจริงจังตาม ข้อบังคับความปลอดภัยของโรงฝึกงาน มีการจัดการซ่อมแซมเครื่องจักรให้อยู่ในสภาพที่ใช้งาน ได้ดี และการใช้เครื่องมือให้ถูกต้องตามลักษณะเครื่องมือแต่ละประเภท ในสภาพแวดล้อมของ โรงฝึกงาน ควรจัดการระบายอากาสให้ถ่ายเทได้ดี และการจัดให้มีปริมาณแสงสว่างอย่างเพียงพอ **Independent Study Title**

Guideline of Accident Protection in Training for

Chiang Mai School of Technology's Students.

Author

Mr.Marust Poophanischarurnkul

M.Ed.

Vocational Education

Examining Committee

Asst. Prof. Dr. Kanya

Kamsiripiman Chairman

Asst. Prof. Manoon

Sutika

Member

Asst. Prof. Apichart

Mackbungwun

Member

Abstract

The purposes of this research were to study the factor causing accidents and percussion measures during the practical training of Chiang Mai Technology students. Data were collected by group sampling using questionnaires with 130 industrial instructors of 1998 academic year and 28 students encountered with the accident during 1997-1998 academic year. The questionnaires were done by the author. The data were analyzed by frequency distribution, percentage mean and standard deviation were calculated.

The results indicated that the accident causing factors during the training course from the unsafe action, for example, lack of safety knowledge, avoidance of rules and regulations of work safety, lack of utilization of personal damage protective tools, unsafe situation e.g. machines are not switch or protective, apparatuses are not well-looked after or efficiency well maintained.

It was suggested that the policy on safety should be clearly directed. The instructor's attitude on safety precautions should be redeveloped. The awareness of the danger during training should be taught. Regulation must be strictly followed. All machines and equipment's must be well maintained and their instructions for use must be followed. Ventilation and illumination in the workshop should be well arranged.