ชื่อเรื่องวิทยานิพนธ์

การศึกษาพฤติกรรมการถ้าและการแตกหักบริเวณผล กระทบจากความร้อนของเหล็กเกรด เอไอเอสไอ 4340 เพื่อปรับปรุงกรรมวิธีการเชื่อมซ่อม

ชื่อผู้เขียน

นายณรงค์ฤทธ์ โทธรัตน์

วิศวกรรมศาตรมหาบัณฑิต

สาขาวิศวกรรมเครื่องกล

คณะกรรมการสอบวิทยานิพนธ์

รศ. ตะวัน สุจริตกุล ประธานกรรมการ ผศ. ดร. อภิวันท์ พลชัย กรรมการ ดร. สุเทพ เลิศศรีมงคล กรรมการ

บทคัดย่อ

วิทยานิพนธ์นี้นำเสนอผลการศึกษา เพื่อกำหนดกรรมวิธีปรับปรุงกระบวนการเชื่อมช่อม เหล็ก เอ ไอเอสไอ 4340 โดยศึกษาพฤติกรรมการล้าและการแตกหัก บริเวณผลกระทบจากความร้อน ผลของกระบวนการเชื่อมทำให้เกิดการเปลี่ยนแปลง โครงสร้างจุลภาคและพฤติกรรมการล้าที่ บริเวณผลกระทบจากความร้อน ชิ้นทดสอบกลุ่มแรกถูกให้ความร้อนก่อนเชื่อมแต่ละชิ้นที่อุณหภูมิ 250°C, 300°C, 350°C และ 380°C ชิ้นทดสอบกลุ่มที่สองถูกให้ความร้อนก่อนเชื่อมแต่ละชิ้นที่ อุณหภูมิ250°C, 300°C, 350°C, 380°C และให้ความร้อนหลังการเชื่อมที่อุณหภูมิ 550°C 1 ชม. รอยบากถูกสร้างขึ้นบนชิ้นทดสอบที่บริเวณผลกระทบจากความร้อนเพื่อกำหนดจุดเริ่มของ รอยแตก การทดสอบหาอัตราการเติบโตรอยแตกทำตาม ASTM E647-95a และทดสอบหาความ แข็งแรงล้าด้วยเครื่องทดสอบความล้าแบบคานหมุน ผลการศึกษาพบว่าความแข็งแรงล้าของ บริเวณผลกระทบจากความร้อน หลังให้ความร้อนหลังการเชื่อมมีค่าน้อยกว่าความแข็งแรงล้าของ เนื้อ โลหะเดิมและมีค่าใกล้เคียงกับความแข็งแรงล้าของบริเวณผลกระทบจากความร้อนที่ให้ความ ร้อนก่อนเชื่อมเพียงอย่างเดียว อัตราการเติบโตของรอยแตกบริเวณผลกระทบจากความร้อนของชิ้น ทดสอบที่ผ่านให้กวามร้อนก่อนเชื่อมอย่างเดียวมีอัตราการเติบโตของรอยแตกน้อยกว่าที่ผ่านให้

ความร้อนหลังการเชื่อม ผลการวิจัยนี้แสคงให้เห็นว่าผลดีที่สุด เกิดที่ให้ความร้อนก่อนเชื่อมที่ อุณหภูมิ 350°C โดยไม่ต้องให้ความร้อนหลังการเชื่อม Thesis Title

A Study of Heat Affected Zone on the Fatigue and Fracture

Behaviors of AISI 4340 Grade Steel for Improvement of

Welding Repair Procedure

Author

Mr. Narongrit Totarat

M.Eng.

Mechanical Engineering

Examining Committee

Assoc. Prof. Thawan Sucharitakul

Chairman

Asst. Prof. Dr. Apiwon Polchai

Member

Dr. Suthep

Lertsrimongkol

Member

ABSTRACT

The attached thesis are the research findings used to improve the practical welding procedures when carrying out welding repairs associated with AISI 4340 grade steel. The research has emphasized on the fatigue and fracture behaviors within the heat-effected zone. The results indicate that the welding process used transformed the microstructure of the material as well as changed the fatigue behaviors in the heat-affected zone. First group of test specimens were pre-heated to 250°C, 300°C, 350°C and 380°C prior to welding, the second were pre-heated to 250°C, 300°C, 350°C and 380°C prior to welding and upon completion test pieces were post-weld heat treated at 550°C for a period of 1 hour. A notch was produced on each test piece at the heat affected zone to initiate the crack. ASTM-E647-95a Standard was used to establish the fatigue crack growth rate. Additionally a rotating bending machine was used to establish the fatigue strength. The results of this research has clearly indicated that the fatigue strength at the heat affected zone from post-weld heat treatment is lower than that of the base metal and is very close to that of the fatigue strength at heat affected zone from pre-heat treatment process only. In addition, the fatigue crack growth rate of the heat-affected zone from pre-heat is lower than that of post-weld heat treatment. Therefore, the research results indicate

that the lowest crack growth rate and best fatigue resistance result from pre-heat treatment at 350 °C without post-weld heat treatment.

